

George R. Reddy

Consulting Geologist

Bus. (505) 623-6233

Res. (505) 623-3767

200 West First Street
Roswell, New Mexico 88201

READ & STEVENS, INC.
Quail State #3Y
Sec. 11, T 19S, R 34E
Lea County, NM

Sidewall Cores

Depth

- 5539 3/4" Rec. SS, lt gry, FG-MG, SA, well srtd, Anhy cmt. fairly friable, questionable lt oil stain, brt yel fluor, good oil show
- 5538 1/2" Rec. SS, AA, good solid yel fluor, both have good cut w/chlorothane.
- 5537 1/2" Rec. SS, AA, good solid yel fluor, has more cmt in matrix, not as friable, sli shaley, dk carbon material (may be on edge of core)
- 5536 1/2" Rec. SS, lt gry, FG, well srtd, clean, SA-R, lt oil stain, good solid yel fluor, good cut w/chlorothane
- 5535 1/2" Rec. SS, lt gry, FG, clean, SA-SR, sli glauc. Tr of stain, scattered yel fluor with good cut.
- 5534 SS, AA, w/good oil stain, solid yel fluor, good cut, has some Dolo, bulk is SS.
- 5533 SS, AA, scat stain, scat fluor, weak cut
-
- 5344 SS, gray, FG, cmtd w/Dolo, SR-SA, N.S.
- 5343 NR
- 5342 SS, VFG, Shaley, gry, N.S.
-
- 5300 SS, FG-MG, Tr porosity, SR, well srtd, appears clean, N.S.
-
- 5296 NR
- 5295 1/2" Rec. SS, very lt gry, silty, VF-MG, Anhy cmt, tight, N.S.
- 5294 1" Rec. SS, silty, lt gry, VF-MG, tight, N.S.
- 5293 1/2" Rec. SS, lt gry, F-MG, Dolo & Anhy cmt, tight, N.S.
-
- 5213 1" Rec. SS, tannish gry, VF-FG, silty, SA-SR, tight, N.S.
- 5212 1/2" Rec. SS, FG, SA-A, very limey, tight, N.S.
-
- 5208 3/4" Rec. SS, AA, very calc.
-
- 5194 3/4" Rec. SS, lt gry, F-MG, very clean, fairly well srtd, SA-SR, looks wet, good porosity, good perm., N.S.