

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR
(Other instruct.
reverse side)CATE
on re-Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM-3622

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Pipeline Deep Unit Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Undesignated
(Quail Ridge Morrow Gas)11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 18, T-19S, R-34E

14. PERMIT NO.

15. ELEVATIONS (Show whether at surface or at depth)

3739' GR

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

COMPLETION

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-15-79 to 5-22-79 Moving out rotary rig.

5-23-79 Moved in and rigged up pulling unit.

5-24-79 Rigged up reverse unit. Ran 4-3/4" bit on 2-7/8" OD tubing. Tested 5-1/2" OD casing to 4000 psi, held 30 minutes. O.K.

5-25-79 Drilled out DV tool and cement inside 5 1/2" OD casing to 13480' PBTD.

5-29-79 Ran Otis Type WB packer on wire line and set at 13318'. Ran 419 jts., 13316' of 2-7/8" OD 6.5# N-80, new tubint set at 13318'.

5-30-79 Latched into packer at 13318'. Installed Xmas tree, tested annulus to 2000 psi, held 30 minutes. O.K. Tested 2-7/8" OD tubing, Xmas tree, and packer to 5000 psi, held 30 minutes. O.K.

6-1-79 Perforated lower Morrow with 2 JSPF from 13388' to 13402'. Testing.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. R. Hughes

TITLE

Dist. Drilling Supt

DATE

June 7, 1979

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE