

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
Union Oil Company of California

3. ADDRESS OF OPERATOR
P. O. Box 671 Midland, Texas 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990' FSL and 1980' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input checked="" type="checkbox"/>

(other) Recomplete in Middle Morrow

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 5-21-83 - MIRUDDPU. POOH w/2-7/8" tbg. Perf Middle Morrow w/4 JSPF from 13,158' - 13,166' - left well open w/no flow for 2 hrs.
- 5-26-83 - Closed well in 17 hrs SITP 1850 psi, opened well to pit on 1/4" chk - well heading w/FTP 1850.psi.
- 5-27-83 - Recovered 5 BLW for 1 hr. Tbg loaded up and died. Ran 1" coiled tbg & jetted tbg dry from 2300' - 10,000'. POOH, well cleaning up w/fine mist w/12'-15' flare. Close well in SITP 900 psi for 13 hrs.
- 5-28-83 - Opened well to pit - flwd on 1/8" chk w/1400# FTP for 5 hrs.
- 5-30-83 - Flwd thru separator @ rate 175-145 MCFD & 2 bbls cond. in 11 hrs. FTP & rate not stabilized. Shut well in.
- 6- 2-83 - Shut-in 62-1/2 hrs - acidized Middle Morrow perfs 13,158'-13,166' w/2500 gals 7-1/2% Morflo acid.

over

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE _____ DATE _____

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

AUG 29 1983

*See Instructions on Reverse Side