

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-26522

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-2519

7. Lease Name or Unit Agreement Name

EAST VACUUM GB/SA UNIT  
TRACT 3467

8. Well No.

001

9. Pool name or Wildcat

VACUUM GRAYBURG/SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Phillips Petroleum Company

3. Address of Operator

4001 Penbrook Street, Odessa, TX 79762

4. Well Location

Unit Letter **B** : **1050** Feet From The **NORTH** Line and **1520** Feet From The **EAST** Line

Section

**34**

Township

**17-S**

Range

**35-E**

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3929' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: **ACIDIZE** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/27/95 MIRU DDU, COOH W/SUB EQPT, GIH W/KILL STRING, TAG @ 2750', SISD.  
10/29/95 COOH W/KILL STRING, GIH W/CSG ROLLER, ROLL OUT BAD SPOT, COOH W/ TBG & COLLARS, SIS  
10/31/95 GIH W/OVERSHOT, COULD NOT GET THROUGH BAD SPOT, RAN IMPRESSION, CSG PROBLEM, SISD.  
11/01/95 NO ACTIVITY.  
11/02/95 MIRU HLS, GIH W/JUNK BASKET, COOH, GIH W/INSPECTION TOOLS, COOH, RDMO HLS,  
GIH W/SWEDGE, WORK SWEDGE IN BAD SPOT, COOH, SISD.  
11/03/95 GIH W/FLAT FACED MILL, TBG, TAG AT 2700', ESTABLISH CIRC, MILL OUT TO 2767',  
COOH, SISD.  
11/05/95 CREW OFF 11-5 & 11-6-95.  
11/07/95 GIH W/BIT, CLEAN OUT FROM 2767' TO 2803', COOH, MIRU HLS,  
CALIBRATE INSPECTION TOOLS, WEIGHT, INDICATOR WOULD NOT  
WORK, RD HLS, SISD. (OVER)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*L. M. Sanders*

TITLE **SR. REGULATION ANALYST**

DATE **11/27/95**

TYPE OR PRINT NAME

**L. M. SANDERS**

TELEPHONE NO. **915/368-1488**

(This space for State Use)

ORIGINAL SIGNED BY JERRY KEATON

APPROVED BY

DISTRICT SUPERVISOR

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 28 1995

EVGSAU 3467-001 CONTINUED

11/07/95	MIRU HLS, RUN CSG, INSPECT. LOG FROM +/- 28001' TO +/- 2800' TO +/- 1900', RDMO HLS, SISD.
11/08/95	GIH W/COLLARS, COOH LD, GIH W/TBG, ND BOP, FLANGE UP WELLHEAD, LEAVE WELL IN "TA" STAT, RDMO DDU.