

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26775
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2360-1
7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit
8. Well No. 001 (Tract 2658)
9. Pool name or Wildcat Vacuum Gb/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, Texas 79762	
4. Well Location Unit Letter <u>K</u> : <u>2500</u> Feet From The <u>West</u> Line and <u>2500</u> Feet From The <u>South</u> Line Section <u>26</u> Township <u>17-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3916.9' GR - 3929' RKB 3919' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Reactivation ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-9-90: Move in WSU. Rig-up tubing B.O.P. and pull tubing. (Recovered Insert Pump.)
10-10-90: GIH w/6-1/8" bit and csg scraper to 4702'. Perf from 4497' to 4502' & 4505' to 4512' w/2 SPF, Total 12' & 24 shots. Rig down. Test csg to 500 psi, OK.
10-11-90: Swab fluid level to 3000 ft. Stimulate well with 2500 gals 15% NEFe with clay stab. and IST and 1200# rock salt. Min. psi 1700-Max psi 2800 - Average psi 1800. ISIP 1600.
10-14-90: Swab 5 hrs.
10-15-90: RD Tbg BOP & RU Rod BOP. Run 2-1/2" X 2" X 22' pump.
10-17-90: RU Electricity. Start well to Pmpg.
10-22-90: Pump 24 hr. 3 BOPD 258 BWPD 1 MCF GOR 328.947 CO2 10.4% Job complete.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Reg. & Proration Supv. DATE 10-24-90

TYPE OR PRINT NAME L. M. Sanders

915-368-1488
TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

007 26 1990