

# INCLINATION REPORT

OPERATOR Phillips 101 Co. ADDRESS Rm 401, 4501 Penbrook St., Odessa, Tx. 79  
 LEASE NAME East Vacuum GB/SA Tract 2957 WELL NO. 002 FIELD Vacuum GB/SA  
 LOCATION Sec 29, T 17 S, R 34 E Lea County

DEPTH	ANGLE INCLINATION DEGREES	DISPLACEMENT	DISPLACEMENT ACCUMULATED
357	3/4	4.6767	4.6767
870	1	8.9775	13.6542
1485	1	10.7625	24.4167
1961	1 1/4	10.3768	34.7935
2186	1 1/4	4.9050	39.6985
2673	1/2	4.2804	43.9789
3209	3/4	6.9561	50.9350
3733	1	9.1790	60.1050
3800	1	1.1725	61.2775
4573	3/4	10.1263	71.4038
4800	1	3.9725	75.3763

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

CACTUS DRILLING COMPANY


Rhonda Ford  
 TITLE Rhonda Ford, Office Manager

**AFFIDAVIT:**

Before me, the undersigned authority, appeared Rhonda Ford  
 known to me to be the person whose name is subscribed herebelow, who, on making  
 deposition, under oath states that he is acting for and in behalf of the operator  
 of the well identified above, and that to the best of his knowledge and belief such  
 well was not intentionally deviated from the true vertical whatsoever.

Rhonda Ford  
 AFFIANT'S SIGNATURE

Sworn and subscribed to in my presence on this the 10th day of September, 1980



SEAL

Notary Public in and for the County  
 of Lea, State of New Mexico