

INCLINATION REPORT

OPERATOR PHILLIPS PET. CO. ADDRESS Rm 401, 4001 Penbrook St., Odessa, Tx, 79762LEASE NAME East Vacuum GB/SA Unit Tract No. 2738 WELL NO. 008 FIELD Vacuum GB/SALOCATION Unit F, 1500' FNL & 2500' FWL, Sec. 27, T-17-S, R-35-E

DEPTH	ANGLE INCLINATION DEGREES	DISPLACEMENT	DISPLACEMENT ACCUMULATED
350	1/4	1.5400	1.5400
900	3/4	7.2050	8.7450
1400	3/4	6.5500	15.2950
1931	3/4	6.9561	22.2511
2399	1	8.1900	30.4411
2899	1	8.7500	39.1911
3399	1	8.7500	47.9411
3896	1 1/4	10.8346	58.7757
4180	1 3/4	8.6620	67.4377
4642	1 1/2	12.1044	79.5421
4750	1 1/2	2.8296	82.3717

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

CACTUS DRILLING COMPANY


Denise Leake
TITLE OFFICE MANAGER

AFFIDAVIT:

Before me, the undersigned authority, appeared DENISE LEAKE
known to me to be the person whose name is subscribed herebelow, who, on making deposition, under oath states that he is acting for and in behalf of the operator of the well identified above, and that to the best of his knowledge and belief such well was not intentionally deviated from the true vertical whatsoever.

Denise Leake
AFFIANT'S SIGNATURE

Sworn and subscribed to in my presence on this the 23 day of JANUARY, 1981



SEAL

Notary Public in and for the County
of Lea, State of New Mexico

72
JUL 1 1981