

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐
well well other

2. NAME OF OPERATOR

Harvey E. Yates Co.

3. ADDRESS OF OPERATOR

P.O. Box 1933, Roswell, NM 88201

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FNL & 660' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) DST #1, Production Csg.

SUBSEQUENT REPORT OF:

RECEIVED
OCT 2 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

5. LEASE
LC-064009-D

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Young Deep Unit

8. FARM OR LEASE NAME

9. WELL NO.

4

10. FIELD OR WILDCAT NAME

No. Young Bone Spring

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 9, T-18S, R-32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3828.3' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5/02/81 Depth 8337', DST #1 8185' to 8337'.

5/04/81 TD 8700'. Logging

5/07/81 TD 8700'.

5/08/81 TD 8700' RD. RR @ 6:00 p. m. 5/7/81.

Ran 8730.64' of 4 1/2" csg and set @ 8700'.

121 jts 10.5# ST&C J-55 (4853.09')

67 jts 11.6# LT&C J-55 (2718.23')

28 jts 11.6# LT&C N-80 (1159.32')

216 jts 8730.64'

Cemented w/700 sx 50/50 Poz w/2% Gel, 6# salt and .3 of 1% CFR-2. Bumped plug @ 1:00 p. m. 5/7/81 w/2000 psi - held o. k.

WAITING FOR COMPLETION UNIT.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I, hereon certify that the foregoing is true and correct

SIGNED

ROGER A. CHAPMAN

TITLE Engineer

DATE May 27, 1981

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY

OCT 6 1981
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

TITLE

DATE