

EXXON COMPANY, U.S.A.

POST OFFICE BOX 10488 • MIDLAND, TEXAS 79702

MIDCONTINENT PRODUCTION DIVISION
SOUTHERN DRILLING ORGANIZATION

E. W. THOMAS, Manager

W. F. BURCHARD, Operations Superintendent
K. S. ROSE, Operations Superintendent
M. C. WELBORN, Operations Superintendent
K. A. WEBER, Engineer Manager

Feb. 22, 1983

LISTED BELOW ARE THE DEVIATION TESTS TAKEN ON NEW MEXICO "DD"
STATE #5 :

<u>DEPTH</u>	<u>DEGREES OF DEVIATION</u>
200	1/2
435	3/4
940	1
1450	1 1/4
1710	1
2008	1/2
2310	1
2632	1
2950	2
3275	2
3476	3
3500	2 3/4
3528	2 3/4
3601	2 1/2
3685	2 1/4
3720	2 1/2
3778	2
3964	1 1/2
4490	1 1/4
4995	1 1/2
5500	1 3/4
5807	1 3/4
6096	1 1/2
6430	1
6930	1
7438	1 1/2
7580	1 1/2
7987	1 1/4
8270	2
8580	4
8705	3 3/4
8800	1 3/4
9070	2 1/4
9361	2 1/4
9590	2 1/4