

UNITED STATES, NEW MEXICO 88240
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

5. LEASE
NM-0554858
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Government "10"
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Scharb (Bone Spring-Wolf)
11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA
Section 10, T19S, R35E
12. COUNTY OR PARISH
Lea
13. STATE
NM
14. API NO.
NA
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3795.9' GR

1. oil well <input checked="" type="checkbox"/> gas well <input type="checkbox"/> other <input type="checkbox"/>
2. NAME OF OPERATOR
The Superior Oil Company
3. ADDRESS OF OPERATOR
P.O. Box 3901, Midland, Texas 79702
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FSL, 660' FWL of Sec. 10
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) Weekly Drilling Recap	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED
JUL 25 1983
SOUTHERN DISTRICT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 7-21-83 Spudded @ 12:00 P.M. 7-20-83, Svy. @ 437' = 1°, drilled to 437', started running 13 3/8" csg.
- 7-22-83 Finished running 13 3/8" csg.
- 7-23-83 Drld cmt and shoe, drld to 1770, svy @ 1406' = 1/2°.
- 7-24-83 Drld to 2385', svy @ 1902' = 0°.
- 7-25-83 Drld to 3286', svy @ 2863' = 1/2°.
- 7-26-83 Drlg @ 3555', svy @ 3378' = 1°.
- 7-27-83 Drlg @ 3922', svy @ 3872' = 1 1/2°.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED G. E. Tate TITLE Div. Opr. Supt. DATE 7-28-83

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

AUG 8 1983

100-100000-100000

100-100000-100000

100-100000-100000

RECEIVED
AUG 9 1983
O.C.D.
HOBBS OFFICE