STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	1	
DISTRIBUTION		
BANTA FE		
FILE	1	
U.S.O.S.		
LAND OFFICE		
CPERATOR	1	1

OIL CONSERVATION DIVISION

<u> </u>	DISTRIBUTION		P O BOX 2088				Form C-103 Revised 10-1-78	
	SANTA FE, NEW MEXICO 87501							
	FILE		4			5a. Indicate		
	U.\$.0.\$.		-			State	Fee X	
⊢	LAND OFFICE		-			5. State Oti 6	Gas Lease No.	
L	OPERATOR		J .					
				D DEDOCT(0)	1 W/F1 1 F	MILLE		
	AND MOT USE THIS	SUND	RY NOTICES AN	D REPORTS ON	WELLS BACK TO A DIFFERENT RESERVOIR.		4//////////////////////////////////////	
	100 101 001	SE "APPLICA	TION FOR PERMIT -" (FORM C-1011 FOR SU	CH PROPOSALS.!	7, Unit Agree	ment Name	
1.	. C. 6/							
*	rece 🔲 w		OTHER-			8. Farm or L	ease Name	
2. Nan	ne of Operator					D 7	Chaha	
	Forest	Oil Co	rporation			9. Well No.	State	
3. Add	tress of Operator					7		
	P. O	Box 191	6 Midland	Texas	79702	10 Field mo	i Pool, or Wildcat	
	cation of Well						1	
	H	.198	80 FEET FA	OM THE NORTH	LINE AND 660 FEE"	Scharb	(Wolfcamp)	
ŭ		· 					VIIIIIIIII	
_	East	LIME SECT	110N 5	TOWNSHIP 195	RANGE 35E N	MPM. () () ()	Ellillillilli.	
7	- 100L	, , 5101					777/1/1/1/1/	
777		777777	15. Eler	ration (Show whethe	DF, RT, GR, etc.)	12. County		
			(IIII)			Lea		
$\frac{222}{16}$	mm	Clark	Appropriate Bo	x To Indicate	Nature of Notice, Report or	Other Data		
				X 10 moreate	SUBSEOU	ENT REPORT	OF:	
	NO.	TICE OF	INTENTION TO:]			
		\Box			REMEDIAL WORK	}	LTERING CASING	
PERF	ORM REMEDIAL WORK	\sqsubseteq	Pi.	UG AND ABANDON	COMMENCE DRILLING OPHS.		LUG AND ABANDONMENT	
7 E M.P	DRABILY ABANDON				CASING TEST AND CEMENT JOB	₹		
PULL	OR ALTER CASING		CH	ANGE PLANS	1			
				_	OTHER			
61	THER				J			
			O (Clearly)	tote all pertinent de	rails, and give pertinent dates, incl	uding estimated dat	e of starting any proposed	
17. D	escribe Proposed or prkj SEZ RULE 10	Completed (Sperditions (Circuity a	state are periment				
	•			11/0//	00 0 111 11501 111	77 1/08 1:		
	11/2/83 -				33. Drill to 450' with			
					casing crew and run l			
K-55, STC csg. Cmt casing with 500 sxs Class C, 2% CaC						$CaCl_2$, $1/4#$	sx flocele mixed	
		at 14	.8#/gal, and	1.32 ft /sx.	Plug down 12:30 AM	11/3/83. WO	C for 24 hrs.	
					BOPs. Test BOPs and o		O psi. Test	
		OK.	RIH with 11"	bit and dril	ll float collar and 50	ft. cement.		
							•	
			: 4	complete to the hea	t of my knowledge and belief.			
18. 1	hereby certify that t	ine informati	ON EDOVE 15 True and	complete to the bea				
	01.	1 1	non		D-41		11/0/02	
516 HE	· Lesu	Mudl	non	TITLE	Petroleum Engineer	DATE	11/8/83	
	ALIPI	IAL CIONS	NEW YEAR YEAR	r ^a				
	OKIGIN	ME SIGNAL.	SUMERVIOLE			N	OV 10 1983	
		Primary Primary	- Commercial Control			DATE	V 7 ~ U 10 VV	