DEPARTM	NITED STATES ENT OF THE INTERIOR LOGICAL SURVEY	Form Approved. Budget Bureau No. 42–R1424 5. LEASE LC - 061154 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICE (Do not use this form for propos reservoir, Use Form 9–331–C for	S AND REPORTS ON WELLS als to drill or to deepen or plug back to a differe such proposals.)	7. UNIT AGREEMENT NAME ent 8. FARM OR LEASE NAME
 ADDRESS OF OPERATION OF BOX 470, A LOCATION OF WELL (F below.) 660' FNL & 	rtesia, New Mexico 88210 REPORT LOCATION CLEARLY. See space 660' FWL n 5. T-18-S. R-32-E	Bassett Birney 9. WELL NO. 1 10. FJELD OR WILDCAT NAME <u>Personal - San Andres</u> 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 5, T-18-S, R-32-E 12. COUNTY OR PARISH Lea New Mexico 14. API NO.
 16. CHECK APPROPRIATE REPORT, OR OTHER REQUEST FOR APPROVAL TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 		CE, 15. ELEVATIONS (SHOW DF, KDB, AND WD) <u>3858.3</u> GL (NOTE: Report results of multiple completion or zone change on Form 9–330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set 1017' of 8 5/8" 23# casing. Cemented with 375 sacks of Hallite plus 150 sacks Class C. Circulated 50 sacks to pit. Waited 18 hours on cement, tested casing to 1500# for 30 minutes with no leakage on May 12, 1984.

Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. I hereby certify that the foregoing is true and correct SIGNED	or date <u>May 14, 1984</u>
ACCEPTED FOR RECORD space for Federal	or State office use)
APPROVED BY	or State office use)
MAY 1 8 1984	
"See Instructions of Cylabad, NEW MEXICO	n Reverse Side

MAY 2 2 1984 HOBBS OFFICE