

Maduro State Com. Well #1

12. Describe Proposed or Completed Operations - Cont.

- 12/11/90 13,400, profile nipple was previously cut off at 13425, btm perfs 13508-24 still covered w/sd and gun debris, circ frac sd out of tbg. Left well flowing to pit, no fluid recovered, flare decreased. SI well.
- 12/12/90 Bled off press from 400 to 0 psi, had weak steady gas blow. Swab. SI well for press build up.
- 12/13/90 Put on line.
- 12/14/90 Compressor down.
- 12/15/90 Compressor down.
- 12/16/90 Shut In Well.
- 12/19/90 Drop from report pending further evaluation.
- 2/13/91 Decided not to do any further work to the Morrow, Well SI, WO unsuccessful.

See C-101 to Plug Back to the Tonto Atoka Gas