

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Pennzoil Company	5. State Oil & Gas Lease No.
3. Address of Operator P.O. Drawer 1828 - Midland, Texas 79702	7. Unit Agreement Name
4. Location of Well UNIT LETTER 0 150 FEET FROM THE South LINE AND 2080 FEET FROM THE East LINE, SECTION 4 TOWNSHIP 175 RANGE 37E NMPM.	8. Farm or Lease Name Viersen
	9. Well No. 3
	10. Field and Pool, or Wildcat Shipp Strawn
15. Elevation (Show whether DF, RT, GR, etc.) 3774.6	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

Drilling Operations

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1/19/87: Ran multi-shot directional surveys from surface to 8865'.
1/23/87: Straighten hole back to vertical with downhole motor.
1/28/87: Straighten hole back to vertical with downhole motor.
2/2/87: Ran multi-shot directional survey from 8865' to T.D. of 11240'.
2/4/87: Ran 275 Jts of 5-1/2", 17#, N-80' & K-55, LTC to 11239'. Cemented with 350 sxs class "H" with .5% CFR-2 plus .4% Halad 9. Cement in place 7:26 AM CST 2-4-87. Estimated TOC-9900'.
2/5/87: Suspended drilling operations - waiting on completion unit.

As per order No. R-8366, Please find enclosed results of directional surveys.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Kautz TITLE Petroleum Engineer DATE 2/6/87
APPROVED BY Paul Kautz Geologist TITLE _____ DATE FEB 10 1987
CONDITIONS OF APPROVAL, IF ANY: