

OIL CONSERVATION DIVISION

P O BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. V-396

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Don R. Ormand	8. Farm or Lease Name Amoco State
3. Address of Operator P.O. Box 3610 ; Midland, TX. 79702	9. Well No. 1
4. Location of Well UNIT LETTER C 560 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 18 TOWNSHIP 17-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat VACUUM (GRAYBURG - SAN ANTONIO)
15. Elevation (Show whether DF, RT, GR, etc.) 4117.7 GR.	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☒	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Total Depth of 4750' REACHED ON 3-19-87. The 4 1/2" PROD. CASING WAS SET AT TOTAL DEPTH & CEMENTED W/ 400 SX. HOWCO LITE plus 300 SX. CLASS C W/ 5" SALT/SX. Subsequent Cement Bond Log indicated cement top AT 2422'. When the cement plug WAS BUMPED AT CONCLUSION OF CONVENTIONAL CEMENT JOB ~~THROUGHOUT~~ A CASING LEAK DEVELOPED & WAS LATER FOUND AT DEPTH OF 1220'-1230'. A secondary cement job WAS DONE IN CONVENTIONAL MANNER FROM 1220' WITH 500 SX. CLASS 'C' CEMENT. Full or estimated 70% RETURNS OCCURRED throughout job. BEADON head WAS CLOSED AND 100 SACKS SQUEEZED AT END OF job. AFTER drilling OUT CEMENT ~~DOWN~~ 1130'-1230' the CASING WAS TESTED TO 650 PSI. FOR 30 MIN.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **Don R. Ormand** TITLE **OPERATOR** DATE **4-27-87**

APPROVED BY **Paul Kauts** TITLE DATE **MAY 1 1987**
Geologist
CONDITIONS OF APPROVAL, IF ANY:

30 1533