

INCLINATION REPORT

OPERATOR:

Sun Exploration & Production Company
P. O. Box 1861
Midland, Texas 79702


LOCATION:

Shoe Bar State Com. #1
Lea County, New Mexico
660' FSL & 2030' FWL,
Sec. 15, T-17-S,
R-35-E.


DEPTH FEET	INCLINATION DEGREES	DEPTH FEET	INCLINATION DEGREES	DEPTH FEET	INCLINATION DEGREES
500	1/4	8,331	1-3/4		
1,003	3/4	8,829	1-1/4		
1,496	1	9,265	1-3/4		
1,916	2-3/4	9,725	1-3/4		
2,073	2	10,229	1-1/4		
2,577	3/4	10,727	1-1/2		
3,060	1-3/4	11,106	1		
3,257	1-3/4	11,238	1		
3,752	1/2	11,386	1		
4,264	3/4	11,564	1-1/2		
4,794	1	12,048	1-1/2		
4,968	1/2	12,248	2		
5,322	1/2				
6,804	1				
7,307	1-1/4				
7,804	1-1/2				

COUNTY OF MIDLAND
STATE OF TEXAS

The undersigned states that he has knowledge of the facts and matter herein set forth and that the same are true and correct.


H. W. McKee, Drlg. Superintendent

SUBSCRIBED AND SWORN TO BEFORE ME THIS 9th day of December 1987


Notary Public

My commission expires: August, 1989