

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30016
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2863-1

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit Tract 3374
2. Name of Operator Phillips Petroleum Company	8. Well No. 004
3. Address of Operator 4001 Penbrook St., Odessa, Texas 79762	9. Pool name or Wildcat Vacuum Gb/SA
4. Well Location Unit Letter <u>L</u> : <u>1950</u> Feet From The <u>South</u> Line and <u>210</u> Feet From The <u>West</u> Line Section <u>33</u> Township <u>17-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3951' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Clean out and acidized ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/28/93 MIRU DDU. NU BOP. COOH with tubing and sub equipment. Catch sample of iron sulfide.  
10/29/93 PU GIH with bit & collars and tag @ 4524'. Clena out to 4690'. Circ clean Pump 20 bbls fresh water with 10 gals TH-430. Mix and pump 3 drums TC-405 with 165 gals fresh water.  
10/29/93 RU swab. Pump 6000 gals 15% NEFE HCL acid.  
10/30/93 PU GIH with sub equip and tubing. ND BOP and PAN. Flange up wellhead.  
11/09/93 Test: Pump 24 hrs 119 BOPD, 143 BWPD, & 34.2 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Supv., Reg. Affairs DATE 11/24/93

TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. 915/368-1488

(This space for State Use)

**ORIGINAL SIGNED BY JERRY SEXTON**  
**DISTRICT I SUPERVISOR**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE DEC 01 1993

CONDITIONS OF APPROVAL, IF ANY:

1998-1999  
1999-2000  
2000-2001

2001-2002  
2002-2003