

NOT KBA 3975.7'
 CHF@
 GL@ 3966.1'

Date: July 1990

Status : P & A

Procedure : Due to various casing Leaks the
 Wellbore was completely filled with
 Cement.

Legal Description: 1533' FEL & 130' FSL
 Unit: 0 Sec: 29 Twn: 17s Rng: 35E
 County: Lea State: NM
 Field: East Vacuum (GR-SA) Unit

Perfs: 4504'-4513'
 4516'-4519'
 4558'-4577'
 4661'-4664'
 4674'-4678'

