

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

API No. 30-025-30073

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 3-4118
7. Unit Agreement Name
8. Farm or Lease Name Lea
9. Well No. 34
10. Field and Pool, or Wildcat Vacuum Grayburg/SA
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

11. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
12. Name of Operator Phillips Petroleum Company
13. Address of Operator 4001 Penbrook Street, Odessa, Texas 79762
14. Location of Well UNIT LETTER <u>N</u> <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>935</u> FEET FROM THE <u>South</u> LINE, SECTION <u>30</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> NMPM

15. Elevation (Show whether DF, RT, GR, etc.)
4089.3 GR (Unprepared)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-28-87: MI & RIJ DDU. Installed 3000 psi BOP. Pressure tested BOP and casing to 3000 psi. Ran GR/Collar locator log from PBTD 4757' to 3500', correlated to open hole CNL-Spectral Density log. Perf'd 4308'-4712' (88'-176 holes).
12-29-87: Acidized perfs w/ 8800 gals 15% NEFe HCl containing fines suspension agent and clay stabilizer. Flow & swbd back well, rec 51 BLW & acid.
12-30-87: Swbd 10 hrs, rec 30 B0, 65 BLW.
1-01 thru
1-04-88: Swbg back load. Frac'd perfs 4308'-4712' w/ 94,000 gals of gelled crosslinked 2% KCl water & 182,000# of 20/40 mesh sand.
1-05 thru
1-12-88: Opened to frac tanks. Swbg back load. WIH w/ 2-3/8" tbg, SN @ 4712', TA @ 4750'. Installed 2-1/2" X 1-1/4" X 20' pmp. Waiting on electrical hook-up.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. J. Mueller TITLE Engineering Supervisor, Resv. DATE 1/15/88
ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT SUPERVISOR TITLE _____ DATE JAN 21 1988

CONDITIONS OF APPROVAL, IF ANY: