Submit 3 Copies to Appropriate District Office	State of New M Energy, Minerals and Natural		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATI P.O. Box 2	088	WELL API NO. 30-025-31455
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexic	o 87504-2088	5. Indicate Type of Lease XXX STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease Na. B-4120
SUNDRY NOT	TICES AND REPORTS ON W	ELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well:			West Lovington Unit
WELL XXX WELL	OTHER		
2. Name of Operator GREENHILL PETROLEUM CORPORATION			8. Well Na. 90
3. Address of Operator 11490 Westheimer, Su	ite 200, Houston, Texa	s 77077	9. Pool mame or Wildcat WEst Lovington Upper San Andres
4. Well Location		2 5 0	0 – North v
Unit Letter \underline{G} : $1,3$	35 Feet From The East	Line and _2,50	0 First From The North Lin
Section 7	Township 17 South	Range 36 East	NMPM Lea County
*******	11/1/1/ 10. Elevation (Show when	her DF, KKB, KI, GK, elc.)	
	3,900	.4 GR	
11. Check	Appropriate Box to Indicat	.4 GR te Nature of Notice, R	Leport, or Other Data
		.4 GR te Nature of Notice, R	Report, or Other Data SEQUENT REPORT OF:
	Appropriate Box to Indicat	.4 GR te Nature of Notice, R	Leport, or Other Data BSEQUENT REPORT OF:
	Appropriate Box to Indicat	.4 GR te Nature of Notice, R SUE REMEDIAL WORK COMMENCE DRILLIN	BSEQUENT REPORT OF: ALTERING CASING [G OPNS. PLUG AND ABANDONMENT [
	Appropriate Box to Indicat NTENTION TO: PLUG AND ABANDON	.4 GR te Nature of Notice, R SUE REMEDIAL WORK	BSEQUENT REPORT OF: ALTERING CASING [G OPNS. PLUG AND ABANDONMENT [

Spud well 03/28/92. Ran 31 joints of 8-5/8" 24# casing and set at 1,310 ft. with 500 sacks of Class "C" cement. Circulate to surface. Waited on cement 13 hours.

Ran 120 joints of 5-1/2" 15.5# casing and set at 5,230 ft. with 1,250 sacks of Class "C" cement. Circulated cement to surface. Waited on cement greater than 24 hours. Tested casing to 2,000 psi. Held OK. Total depth 5,230 ft.

I hereby certify that the information above is true and complete to the best of my known signature	wkedge and bedief. Land MgrPermian Basin	date 4/22/4 2 Telephone no.713_589-8484
(This space for State Use)	TITLE	MAY 0 4'92

Tested casing to 800 psi. Held OK.