


Mallon Oil Company
999 18th St., Ste 1700
Denver, CO 80202

Mallon 34 Federal 9
Lea County, NM

Unit G
34-195-34e

1980/N 4 1980/E
30-025-32784


476	4.76	3/4	1.31	6.25	6.25
976	5.00	3/4	1.31	6.56	12.81
1502	5.26	1	1.75	9.21	22.02
1973	4.71	1/2	0.88	4.12	22.39
2446	4.73	2	3.50	16.56	42.69
2705	2.59	1	1.75	4.53	47.22
2877	1.72	1	1.75	3.01	50.23
3006	1.29	2 1/2	4.38	5.64	55.88
3135	1.29	2 3/4	4.81	6.21	62.09
3264	1.29	2 3/4	4.81	6.21	68.29
3436	1.72	2 1/4	3.94	6.77	75.07
3651	2.15	1 1/4	2.19	4.70	79.77
4060	4.09	1	1.75	7.16	86.93
4555	4.95	1	1.75	8.66	95.59
5027	4.72	3/4	1.31	6.20	101.78
5544	5.17	1 1/2	2.63	13.57	115.36
5706	1.62	3/4	1.31	2.13	117.48
6203	4.97	1	1.75	8.70	126.18
6676	4.73	1 3/4	3.06	14.49	140.67
7150	4.74	2 1/4	3.94	18.66	159.33
7723	5.73	2 1/2	4.38	25.07	184.40
8120	3.97	1	1.75	6.95	191.35
8200	0.80	1	1.75	1.40	192.75


James L. Brazeal - President

STATE OF TEXAS }
COUNTY OF COLLIN }

The attached instrument was acknowledged before me on the 8th day of May, 1995 by James L. Brazeal as President of BRAZEAL, INC. d/b/a CapStar Drilling

SEAL




Paula Carlisle - Notary Public

RECEIVED

JUL 08 1985

UCD HUBBS
OFFICE

May 31, 1995

WELL NAME AND NUMBER: Mallon 34 Federal #9
LOCATION: SEC 34 T19S R34E Lea Co.
OPERATOR: Mallon Oil Company
DRILLING CONTRACTOR: ZIADRIL, INC.

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above described well and that he has conducted deviation tests and obtained the following results:

<u>DEGREES AND DEPTH</u>	<u>DEGREES AND DEPTH</u>
--------------------------	--------------------------

.50	8635'
1.00	9130'
1.75	9779'
1.75	10355'

Drilling Contractor: ZIADRIL, Inc.

By

Billy Jensen
Billy Jensen

Subscribed and sworn to before me this 31st day of May, 1995.

My Commission Expires:
September 13, 1996

Virginia B. Perry