

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32935
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	16969

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Pearl State
2. Name of Operator Stevens & Tull, Inc.	8. Well No. 1
3. Address of Operator P. O. Box 11005, Midland, Texas 79702	9. Pool name or Wildcat Pearl Queen
4. Well Location Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line Section 36 Township 19S Range 34E NMPM County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3720 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Production Casing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/16/95 TD Well at 5300'

5/17/95 Run 127 jts of 5 1/2" -17#, J-55, LTC new casing and set at 5296'.
Cement w/ 1300 SX 35/65 POZ "C" + 6% D20 + 3% D44 + 1/4 #/SX celloflake followed
w/ 200 SX tail 50/50 POZ "C" + 2% D20 + .5% D112 + 3% M117 total 250% excess.
Cement did not circulate to surface - lost returns. SI for 48 hours before
starting completion.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael G. Mooney TITLE Engineer DATE 5/18/95
TYPE OR PRINT NAME Michael G. Mooney TELEPHONE NO. 915/699-141

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 22 1995

CONDITIONS OF APPROVAL, IF ANY: