Deviation surveys taken on Eurlington Resources! Mule Deer "36" State #6 well in Lea County, New Mexico: Unit 9 36.22-37 330/5 \$1980/E

	•
Depth	Degree
200	.25
258	. 25
317	1.00
343	. 50
402	. 75
461	.75
514	1.00
720	.25
783	1.00
867	1.50
933	2.00
1027	1.00
1242	. 75
1490	1.00
1738	.75
2077	.75
2448	.25
2821	. 50
3248	1.25
3506	1.00
3754	.50
4035	. 75
4376	2.25
4529	3.00
4591	3.00
5010	. 75
5498	. 75
6005	. 75
6492	. 75
6985	.25
7483	. 50
7987	.75
8480	.75

I hereby certify that I have personal knowledge of the facts placed on this sheet and that such information given above is true and complete.

Moston Drilling Company

Before me, the undersigned authority, on this day personally appeared John W. Norton, known to me to be the person whose name is subscribed hereto, who, after being duly sworn, on oath states that he is the drilling contractor of the well identified in this instrument and that such well was not intentionally deviated from the vertical whatsoever.

John W. Norton