Submit 3 Copies to Appropriate District Office

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I OIL CONSERVATION DIVISION WELL API NO. P.O. Box 1980, Hobbs NM 88240 P.O. Box 2088 30-025-33417 DISTRICT II Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE X FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) HALE. M. E. 1. Type of Well: OIL WELL X WELL | 2. Name of Operator 8. Well No. Phillips Petroleum Company 025 3. Address of Operator 9. Pool name or Wildcat 4001 Penbrook Street, Odessa, TX 79762 VACUUM GRAYBURG/SAN ANDRES 4. Well Location P : 1170' Feet From The SOUTH 660' Unit Letter Line and EAST Feet From The Line Township 17-S Range 34-E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4008' GL Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING TEMPORARII Y ARANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: COMPLETION OTHER: _ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. MIRU DIAMOND DDU, NU BOPE, TIH W/SCRAPPER TO 4585', CIRC 140 BBLS WATER, RU HES, 08/05/96 RUN GAMMA LOG, PERF 4464'-4476', 12', 24 SHOTS @ 2 SPF, RUN KILL STRING, SDON. TEST 2-7/8" TBG IN HOLE, SET PKR @ 4393', MIRU CHARGER, PUMP 1000 GALS 15% HCL, 08/06/96 FLUSH W/28 BBLS WATER, RU SWAB, OPEN WELL, FLOW 20 BBL OF FLUID, RECOVER TOTAL 70 BBLS, TRACE OF OIL, SDON. SWAB PERFS 4464'-4476', SWAB 70 BBLS WATER, 9 BO, RU JARREL WIRELINE, GIH W/GUAGES 08/07/96 TO 4470', SDON. COOH W/GUAGES, COOH W/PKR, MIRU HES, PERF 4373'-4388', 15', 20 SHOTS @ 2 SPF, GIH 08/08/96 W/RBP-PKR, SET @ 4400', TEST OK, MIRU CHARGER, SPOT 2 BBL 2 BBL ACID ON PLUG. POOH TO 4298', SET PKR, PUMP 25 BBL ACID, RC CHAGER, OPEN WELL, RU SWAB, RECOVER 30 BBL, SDON. (OVER) I hereby certify that the information above is true and complete to the best of my knowledge and belief. ____ τπιε <u>Senior Regulation Analyst</u> DATE_ TYPE OR PRINT NAME Larry M. Sanders TELEPHONE NO. (915) 368-1488 (This space for State Use)

- HALE, M. E. WELL NO. 025 PAGE 2.
- 08/09/96 SWAB BACK 176 BBLS TOTAL, 13 BBLS OIL, SDON.
- 08/10/96 SWAB BACK 4 BBL OIL, 80 BBL WATER, GIH W/GUAGES TO 4380', SDON.
- 08/11/96 COOH WGUAGES, COOH W/PKR & TBG, GIH W/2-7/8" PROD TBG, LANDED @ 4458', TAC @ 4294', ND BOPE, NU WELLHEAD, SDON WAITING ON RODS.
- 08/13/96 GIH W/ROD STRING & PUMP, RD DIAMOND DDU, WELL SHUT IN WAITING ON PUMPING UNIT, POWER, FLOWLINE, TEMP. DROP FROM REPORT.
- 08/19/96 INSTALL ROTAFLEX PUMPING UNIT, HOOK UP POWER, WELL PUMPING TO BATTERY, 24 HRS TEST, 4 BO, 80 BW, 5 MCF.
- 08/20/96 TEST 24 HRS, 2 BOPD, 350 BWPD, 1 MCF. COMPLETE DROP FROM REPORT.