

**MALLON OIL COMPANY
Mescalero 30 Federal No. 4
SWNE Section 30-T19S-R34E
Lea County, New Mexico**

ATTACHMENT A

	Strawn	Morrow
Measured bottom hole flowing pressure, psi	--	1200
Estimated bottom hole flowing pressure, psi	1200	--
Measured original shut-in bottom hole pressure, psi	6462	7000