TMBR/SHARP DRILLING, INC. <u>Angel "13" State No. 2</u> 2310' FNL & 2310' FEL Sec. 13, T-17S, R-35E Lea County, NM

- 10/31/00 SITP 110 psi, SICP 380 psi.
 Bled down. GIH w/swab, FL 4300'. 1st run 30% oil. 2nd run FL 4600', 10% oil. Made 8 more runs, FL 5800', oil cut increased to 30%. ND WH, NU BOP. Release TAC. Tag TD, no fill. POH w/tbg. PU BOP, 1 jt 2⁷/₄" tbg, perf sub, SN, 6 jts 2⁷/₄" tbg, TAC, remainder of tbg, GIH. ND BOP. Set TAC @ 12,000# tension @ 6974', SN @ 7160'. NU WH. Secure well. SD @ 6:30 PM. Rec 87 BBL, total recovered 1213 BBL, 392 BLWTR.
- 11/01/00 SITP 50 psi, SICP 0 psi.
 RD Pool Well Service. Move to Angel "13" State No. 1. RU, pull rods & pump. RD, move to Angel "13" State No. 2. RU Pool Well Service. PU 2½" x 1¼" x 20' RHBC pump. GIH w/198 ¾" used grade "D" rods. Secure well. SD @ 6:15 PM.
- SITP 50 psi, SICP 50 psi. GIH w/new ¾" rods, space out pump. Load tbg w/2% KCL, press to 50 psi, ok. Stroke pump w/unit w/4 strokes, pump press increased to 500 psi. Secured well. RD Pool Well Service. Build pad for battery, set 2 500 BBL tanks. Stack tanks, heater treater & separator. Set pad for pump jack.

Tubing Detail:		
1 - jt 21/8" 6.5# J-55 wBP	31.87	7192.95
1 - 21⁄8″ API SN	.88	
6 - jts 21⁄8″ 6.5# J-55 new tbg	190.13'	7160.20
1 - 5½" x 2%" TAC	3.12	
219 - jts 27⁄8″ 6.5# J-55 new tbg	6952.95	
KB to GL	14.00	
Rod Detail		
1 - 8' x 1" g as anchor	8.00	
1 - 2½" x 1¼" x 20' RHBC pump	20.00	
198 - ¾" x 25' used grade D rods	4950.00	
87 - 1/8" x 25' new grade D rods	2175.00	
3 - 7¾" pony rods (2', 4', 6')	12.00	
1 - 1¼" x 22' polish rod w/1½" liner	22.00	

- 11/03/00 Set Emsco 320 pump jack & base. Replace base on heater treater, set on foundation. Install dump valves, battery 30% complete.
- 11/04/00 Hook up lines to production & wtr lines. Lay flow line from well to separator. Battery 60% complete.
- 11/05/00Hook up wellhead, bypass lines on heater-treater. Pumper will pump well into stack tanks direct.
Will sandblast & coat heater-treater 11/06/00, weather permitting. Battery 90% complete.
DCC: \$ 5,250DCC: \$ 190,860
 - In 24 hrs made 6 BO & 96 BW. Belts off unit; had gang to re-install belts; restarted.
- 11/06/00 In 24 hrs made 6 BO & 52 BW. Pump was not pumping had trash in it. Lowered pump to tag. Pumping ok, action weak.

3