		<b>n</b> .		and the second		
ora - 351 May 1963)	UNIT	• • • • • • • • • • • • • • • • • • • •	SUBMIT IN FRICLIN		42-R1424.	
		OF THE INTER	IOR verse side)	5. LEASE DESIGNATION AND SE	RIAL NO.	
	GEOLO	GICAL SURVEY		NM-2951	····	
SUND	6. IF INDIAN, ALLOTTEE OR TR	THE NAME				
(Do not use this fo	use "APPLICATION F	or to deepen or plug OR PERMIT—" for such p	back to a different reservoir. proposals.)	•		
				7. UNIT AGREEMENT NAME	7. UNIT AGREEMENT NAME	
NAME OF OPERATOR (Re-entry)					Teas Yates Unit	
				8. FARM OR LEASE NAME		
Anadarko Production Company				9. WELL NO. 14		
P. O. Box 806, Eunice, New Mexico 88231 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' FSL and 2310' FEL				2		
				10. FIELD AND POOL, OR WILDO	CAT	
				Teas Yates		
				11. SEC., T., R., M., OR BLK. AND SUBVEY OR ABEA	)	
				14-T20S-R33E		
, PERMIT NO.	15. EI	EVATIONS (Show whether D	F, RT, GR, etc.)	12. COUNTY OR PARISH 13. S	TATE	
Dated 5-13 74	30	502' DF		Lea N.	Mexic	
	Check Approprie	ate Box To Indicate I	Nature of Notice, Report	• •		
NO	TICE OF INTENTION TO			SUBSEQUENT REPORT OF :		
TEST WATER SHUT-OFF		ALTER CASING	WATER SHUT-OFF	<b>See</b>	<u> </u>	
FRACTURE TREAT		COMPLETE	FRACTURE TREATMEN	A REPAIRING WELL		
SHOOT OR ACIDIZE	ABANDON	•	SHOOTING OR ACIDIZI	· · · · · · · · · · · · · · · · · · ·		
REPAIR WELL	CHANGE	PLANS	(Other)			
(Other)			Completion or I	results of multiple completion on Wel Recompletion Report and Log form.) t dates, including estimated date of str vertical depths for all markers and ze		
followed by surface. Shut in 24	v 131 sks Cl hours wait:	lass "C" neat	Pressure test	Gel & 2% Cacl, nt circulated to ed casing to 600 ps	<b>i</b>	
3. I hereby certify that t SIGNED (This space for Federa APPROVED BY CONDITIONS OF APP	l or State office use)		rea Supervisor	MOSEDITE ESA RECORD		
				SEP die 1954	1	
		*~ ·		U. S. GEOLOGICAL OURVEY	ì	
		TSee Instruction	ns on Reverse Side	HOBBS, NEV/ MEXICO		