

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office New MexicoLease No. NM-0890-CUnit Federal

RECEIVED

NOV 2 1960

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT..... X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 10, 1960

Well No. 1 is located 660 ft. from N line and 1980 ft. from W line of sec. 35NE/4 of NW/4 Sec 35
($\frac{1}{4}$ Sec. and Sec. No.)20-S 3-E
(Twp.) (Range)NMPM
(Meridian)Wildcat
(Field)Lea
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 3670 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spotted 12 sacks of cement in bottom of casing with tubing, hole filled with mud. Shot casing free at 2486' and pulled casing out of hole. Spotted 12 sack plug at 2480'; 40 sack plug 1600-1450'; 40 sack plug 750-600'; 10 sack plug at top of surface and erected monument as specified. Casing and Equipment moved off lease and pits covered and cleaned up.

RECEIVED

OCT 14 1960

U. S. GEOLOGICAL SURVEY
ARTERY, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Cince Production Co., LtdAddress Box 1026Midland, TexasBy Bill GreenTitle Office Manager