


HOLD OFFICE COPY

Form 9-521a
(Feb. 1959)

Budget Bureau No. 49-2384
Approval expires 12-31-60



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lead Office **LAS CRUCES**

Lease No. **065607**

Unit **NPH**

RECEIVED

OCT 20 1959

U. S. GEOLOGICAL SURVEY
LAS CRUCES, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 8th, 19 59

Matlock

Well No. 2 is located 1994.4 ft. from [N] line and 1980 ft. from [W] line of sec. 4

SE/NE Sec. 4
(of Sec. and Sec. No.)

20S
(Twp.)

34E
(Range)

NMPM
(Meridian)

Redesignated
(Field)

Lee
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3639 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was plugged on October 5, 1959, as follows:

25 sacks of cement were spotted from 3755-3680

35 sacks of cement were spotted from 3200-3100

35 sacks of cement were spotted from 1650-1550

50 sacks of cement were spotted from 868-768

25 sacks of cement were spotted at surface. A four inch marker was placed at surface of hole. As soon as location has been cleaned off you will be notified.

*Completed 10/16/59
to her cleanup*

L.R. Z. [unclear] when notified.

*has been
cleaned up better*

Bring & leave equipment at [unclear] near location (have in production)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company WILLIAM A. & EDWARD R. HUDSON

Address 1810 ELECTRIC BUILDING
FORT WORTH, TEXAS

[Signature]

Title Partner