

(SUBMIT IN TRIPLICATE)

U. S. Land Office... Las Cruces  
Lease or permit No. 029518. (a)  
J.S. Lea (a) Lease

.....  
Allottee.....  
Lease No.....  
**UNITED STATES**  
**DEPARTMENT OF THE INTERIOR**  
**GEOLOGICAL SURVEY**

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

**RECEIVED**  
**SEP 6 1938**  
**HOBBS OFFICE**

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Wink, Texas September, 2, 1938

J.S. Lea (a)

Well No. 3 is located 440 ft. from N line and 440 ft. from E line of sec

NE 1/4 - SW 1/4 of Sec. 14 20 S. 34 E. N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

North Lynch Lea County New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3654 ft.

**DUPLICATE**

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

At a total depth of 3708' in sand and lime, this well showed 100% salt water on a bailing test. This well has been plugged and abandoned as follows.

Plugged back to 3690' with rock and from 3690' to 3686' with 300# of lead wool and to 3616' with cement. The hole was mudded to the bottom of the 7" at 3529' and 10 sacks of cement spotted in the bottom of the pipe. After pulling 2486' of the 7" casing the hole was mudded to the bottom of the 8-5/8" at 1561' and 10 sacks of cement spotted in the bottom of the 8-5/8". After pulling 693' of the 8-5/8" casing the hole was mudded to the surface and the customary 4" pipe marker set and cemented in the top of the hole with 10 sacks of cement. Plugging and abandoning was completed and the location cleaned up on 8-29-38.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Drawer K

Wink, Texas

By [Signature]

Title District Superintendent

10-10-1964

STADLER, J. C.