

(Nov. 1936)

Indian Agency.....

(SUBMIT IN TRIPLICATE)

S. Land Office **Las Cruces**Lease or permit No. **029518**

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Allottee.....

Lease No.....

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT..... X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Wink, Texas **August 11**, 19 **37****J.S. Lea**Well No. **2** is located **1980** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **15****SE $\frac{1}{4}$ of NE $\frac{1}{4}$ of Sec. 15** **20 S.** **34 E.** **N.E.P.M.**

(¼ Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

North Lea

(Field)

Leas

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **3655** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

The hole was filled with heavy mud to the surface and a cement plug spotted in the bottom of the 7" casing from 3532' to 3482' on 8-5-37.

After parting and pulling the 7" casing from 2533', and filling the hole with heavy mud, a cement plug was spotted in the bottom of the 8-5/8" casing from 1665' to 1632'.

The 8-5/8" casing was parted and pulled from 657' and the hole filled with mud to the surface.

Completed plugging and abandoning the well by cementing customary 4" pipe marker in the top of the 13" surface casing, on 8-10-37.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations **AUG 18 1937** commenced.Company **The Texas Company**Address **Drawer K****Wink, Texas.**By *[Signature]*Title **District Superintendent.**