

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Sante Fe
Lease No. LC061144.A
Unit K
1962 JUL 1 AM 8 01

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	X	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 24, 19 62

Well No. 1 is located 1650 ft. from S line and 2310 ft. from W line of sec. 22
SW/4 Sec 22 20-5 34-E NMPN
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
North Lynch Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

Ground
The elevation of the ~~derick~~ floor above sea level is 3654 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded : 12:20 P. M., 6-27-62

Surface casing: 8-5/8", 24#, J-55 set @ 1650. Cemented with 440 sacks 4% Gel which is 50% excess per USGS requirements. Did not circulate; gravel packed to surface. WOC 24 hrs. Pressure tested to 1000 #. Held O.K.


I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company L. R. French, Jr., Agent for Lucy R. Muse

Address Box 591

Odessa, Texas

By L. N. Dunnivant
L. N. Dunnivant
Title Production Superintendent



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Sante Fe
Lease No. LC061144.A
Unit K

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	X	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 24, 19 62

Well No. 1 is located 1650 ft. from S line and 2310 ft. from W line of sec. 22
SW/4 Sec 22 20-5 34-E NMPN
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
North Lynch Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

Ground

The elevation of the ~~device~~ floor above sea level is 3654 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded : 12:20 P. M., 6-27-62

Surface casing: 8-5/8", 24#, J-55 set @ 1650. Cemented with 440 sacks 4% Gel which is 50% excess per USGS requirements. Did not circulate; gravel packed to surface. WOC 24 hrs. Pressure tested to 1000 #. Held O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company L. R. French, Jr., Agent for Lucy R. Muse

Address Box 591

Odessa, Texas

By L. N. Dunnivant
 Title L. N. Dunnivant
Production Superintendent