(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office			
Lease No. NN-()1130			
Unit			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS. NOTICE OF INTENTION TO TEST WATER SHUT-OFF. NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL. NOTICE OF INTENTION TO SHOOT OR ACIDIZE. NOTICE OF INTENTION TO PULL OR ALTER CASING. NOTICE OF INTENTION TO ABANDON WELL.	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT
	K NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. $\frac{1}{W}$ is located $\frac{330}{W}$ ft. from $\frac{N}{W}$ line of sec. $\frac{29}{W}$ NW/4 Sec 29 20 S (% Sec. and Sec. No.) (Twp.) (Meridian) (Range) Undesignated New Mexico (Field) (County or Subdivision)

The elevation of the derrick floor above sea level is 3674 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

Drilled 6 1/4" hole to 3541 in Lime. Cut and pulled 7" casing from 25'50 feet. Ran 4 1/2" 9.5# caming to 3540 and cemented with 600 sacks 50/50 Pozniz plus 6% Gel and 50 sacks regular with 45 gallons Latex. Maximum pump pressure 1150%. Plug dow n 1:45 A.M. 7/18/61. Released pressure after 12 hours and ran temperature survey - top of cement behind pipe 500 feet. On 7/20/61 pressure tested casing with maximum 3500, , test 0.K. Pressure test witnessed by Mr. E. W. Standley, USGS.

I understan	d that this plan of work must receive approval in writ	ting by the Geological Survey before operations may be commenced.
Company	Earl G. Colton	the commenced.
Address	c/o 011 Reports	
	Box 763	By Adu And
	Hobbs, New Mexico	Title agent