

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Resler & Sheldon, 302 Carper Building, Artesia, New Mexico
(Address)

LEASE Lea State WELL NO. 1 UNIT E S 32 T 20 R 34

DATE WORK PERFORMED April 1, 1957 POOL Wildcat

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Ran 25 sax cement plug from 3545-3621'. Filled to 3285 w/mud. 25 sax cement from 3285-3210. Filled to 1675 w/ mud and put 25 sax cement from 1675-1625'. Then pulled 10 3/4" casing and set cement bridge from 55' to 65'. Pulled the 13 3/8" casing and set 4" marker on the surface in concrete.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	_____	_____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Sanford H. H. H.
Title _____
Date _____

Name Vilas Sheldon
Position Partner
Company Resler & Sheldon