

N. M. OIL & GAS COMMISSION
P. O. BOX 1000
HOBBS, NEW MEXICO 88240

Form 9-331
Dec. 1973

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ well ☐ other ☐ SWD Well

2. NAME OF OPERATOR
TEXACO USA

3. ADDRESS OF OPERATOR
P.O. Box 728, Hobbs, N.M. 88241-0728

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL, 1980' FEL Unit Ltr G
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☐
☐
☐
☒
☐
☐
☐
☐

5. LEASE
LC-029519-a

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
B.V. Lynch "A" Fed

9. WELL NO.
11

10. FIELD OR WILDCAT NAME
Lynch Yates - 7-Rivers

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 34 T-20-S, R-34-E

12. COUNTY OR PARISH
Lea

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3732' DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU pulling unit. Pressured up on 5 1/2" csg. to 500# with steady leak-off.
2. Attempted to release Guiberson pkr. @ 3205' but would not unset. Backed off 3200' of 3 1/2" fiberglass tubing and TOH.
3. TIH w/2 7/8" workstring and mill. Milled on pkr. with little progress. Ct returns of casing cmt. and formation.
4. Retagged pkr. @ 3205', no progress. TOH w/mill and workstring.
5. RD pulling unit. SI well pending evaluation.

ACCEPTED FOR RECORD

SWD
NOV 4 1985

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct.

SIGNED R. Frank Gray TITLE Dist. Opr. Mgr. DATE 5/6/85

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 7 - 1985

CCO.
HODS OFFICE