



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **LC-029519(a)**

Lease No. **11110 07-105-600**  
Unit **1517 OCT 30 PM 2:45**

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	<b>Notice of cementing of casing x</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Boulah V. Lynch (a)**

**Midland, Texas**

**10-23, 1957**

Well No. **12** is located **330** ft. from **N** line and **330** ft. from **E** line of sec. **34**

**NE 1/4 Sec. 34**  
(1/4 Sec. and Sec. No.)

**20-E**  
(Twp.)

**34-E**  
(Range)

**106PM**  
(Meridian)

**Lynch**  
(Field)

**Lee**  
(County or Subdivision)

**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is **3710** ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Ran 115 lbs 3669' of 5 1/2" cas set @ 3679' with 1000 Sx, 4 1/2", and 200 Sx Reg. by HOWCO. Did not circulate. Spotted 250 Sx cement on outside of casing to complete fill up.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Texas Company**

Address **Box 1270**

**Midland, Texas**

By 

Title **Asst. Dist. Supt.**