


(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. NM 0897

Unit Lease

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SEP 21 AM 9:40



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 18, 1956

Fletcher "A"

Well No. 1 is located 990 ft. from N line and 990 ft. from E line of sec. 35

NW/4 Section 35
($\frac{1}{4}$ Sec. and Sec. No.)

20 S
(Twp.)

34 E
(Range)

NMPM
(Meridian)

Lynch
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3730 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 16-inch hole 8:00 A.M. 9-17-56. Found top Red Bed 35 feet. Mudded 13 3/8-inch 42# casing at 70 feet with 15 sacks Milgel. Bailed hole dry and let stand 5 hours. Drilled out of 13 3/8-inch casing with 12 1/4-inch bit.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Drilling & Exploration Company, Inc.

Address Box 2075

Hobbs, New Mexico

By D. C. Smith

Title Division Production Superintendent