


Form 100-1001  
(Rev. 1951)



(SUBMIT TO OFFICE OF, C. C.  
HOBBS, CHIEF)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Approval expires 12-31-66.  
Land Office New Mexico  
Lease No. NM 08823  
Unit \_\_\_\_\_

MAR 29 11 54 AM '66

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

\_\_\_\_\_ April 22 \_\_\_\_\_, 1965

Well No. 1 is located 330 ft. from S line and 1650 ft. from W line of sec. 35

\_\_\_\_\_ 20-S \_\_\_\_\_ 34-E \_\_\_\_\_ NMPM  
(Twp.) (Range) (Meridian)  
\_\_\_\_\_ Lynch \_\_\_\_\_ Lea \_\_\_\_\_ New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3804 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

25 sack plug from 3544-3757'

10 sack plug from surface to 85'

Cut off casing and welded marker on cap

Cleaned up location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MALLARD PETROLEUM, INC.

Address 1206 V & J Tower

Midland, Texas

By R. W. Keener

R. W. Keener

Title Production Superintendent

APPROVED

MAR 24 1966

J. L. GORDON  
ACTING DISTRICT ENGINEER