

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator		EAST PEARL QUEEN UNIT
3. Address of Operator		8. Farm or Lease Name
SHELL WESTERN E&P INC		EAST PEARL QUEEN UNIT
4. Location of Well		9. Well No.
P.O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)		43
UNIT LETTER <u>E</u> 1980 FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM		10. Field and Pool, or Whicet
THE <u>WEST</u> LINE, SECTION <u>34</u> TOWNSHIP <u>19-S</u> RANGE <u>35-E</u> N.M.P.M.		PEARL QUEEN
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3703' DF		LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	TEMPORARILY ABANDONED <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-18-85: Pulled production equipment. Ran gauge ring & junk basket to 4700'. Set a CIBP @ 4670' and capped w/21' (2 sx) cmt.

11-19-85: Circ'd inhibited wtr, tstd CIBP & csg to 300#, held OK. Well is now temporarily abandoned.

Expires 12/6/86

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seay A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE DECEMBER 6, 1985

Eddie W. Seay
Oil & Gas Inspector

DEC 9 - 1985

APPROVED BY _____ TITLE _____ DATE _____