

BBS OFFICE COPY

(SUBMIT IN TRIPLICATE)

Approval expires 12-31-55.

Land Office New MexicoLease No. 06413

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

DEC 1 1958

NOV 11 1958

1958

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Cactus Drilling Company #1 Featherstone-Federal

November 6, 1958

, 19____

Well No. 1 is located 660 ft. from [N] line and 660 ft. from [E] line of sec. 6
NE/4 NE/4 Sec. 6 20 S 35 E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Lea County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3700 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Under verbal authority of Mr. Thomas Godfrey as per telephone conversation of November 4, 1958, this well was plugged and abandoned in the following manner:

Set 15 sacks of cement at bridge plug set at 4850'. *about 11' from surface*
 Set 20 sacks of cement at 5 1/2" casing stub at 4300'. *about 5' from surface*
 Set 20 sacks of cement at Base of salt at 3440'.
 Pulled 8 5/8" casing, leaving bottom joint in hole.
 Set 20 sacks of cement at top of salt at 1860'.
 Set 15 sacks of cement in and out of 13 3/8" surface casing at 90' and filled to surface.
 Set regulation marker at surface. *3-6-59 Salt Marker OK.*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Cactus Drilling CompanyAddress Box 1826Hobbs, New MexicoBy George P. SmithTitle Vice-President