

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 04776-A
Unit U.SIA. West Monument

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 2, 1951

Well No. 1 is located 660 ft. from N line and 660 ft. from W line of sec. 23
G/NW/4 NW/4, Sec. 23 20-S 35-E N.M.P.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wladcat Lea County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1970' - Total Depth - Anhydrite. Finished drilling 9-7/8" hole at 3:18 P.M., 4-1-51. Ran 7-5/8" casing & set at 1959' & cemented with 700 sacks of Trinity Reg. & 50 sacks of Incor cement - total of 750 sacks cement. Plug to 1915' at 2:40 A.M., 4-2-51, with 750# maximum pump pressure. Cement circulated. Will wait on cement 60 hours and test for water shut-off.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Amerada Petroleum Corporation

Address Drawer D

Monument, New Mexico

By

Title Assistant District Superintendent