Submit 3 Copies	State of N	ew.Merico	
to Appropriate District Office	State of Nev-Mexico En. , Minerals and Natural Resources Department		Form C-103 Revised 1-1-89
DISTRICT] P.O. Box 1980, Hobbs, NM \$8240 OIL CONSERVATION DIVISION			
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			WELL API NO.
DISTRICT II		30-025-04170	
P.O. Drawer DD, Artesia, NM 88210		0150+2000	S. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Azec, NM 87410		STATE STATE	
			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			B-1936
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)			···
1. Type of Well:			
			NORTH MONUMENT G/SA UNIT BLK 18
2. Name of Operator			8. Well No.
AMERADA HESS CORPORATION 3. Address of Operator			12
POST OFFICE DRAWER D. MONIMENT NEW MEXICO BOOCH			9. Pool same or Wildcat
			EUNICE MONUMENT G/SA
Unit Letter L : 2310 Feet From The SOUTH Line and 990 Feet From The WEST Line			
Section 2 Township 205 D DCT			
County 10. Elevation (Show whether DF, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	PLUG AND ABANDON		
	CHANGE PLANS		
PULL OR ALTER CASING		CASING TEST AND C	
OTHER:			INTEGRITY TEST.
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
NMGSAU #1812 08-04-93 Thru 08-05-93			
X-Pert Well Service rigged up pulling unit and TOH with a 1-1/4" x 26' polished rod,			
7/8" x 6' pony rod, 12 7/8" sucker rods, 137 3/4" sucker rods, 3/4" x 2' pony rod, and a 2" x 1-1/4" x 10' pump. Removed 8-5/8" Larkin-Hinderliter tubinghead packing and slip assembly and installed an 8-5/8" Larkin dentant filter tubinghead packing and			
set at 3,824' in 1954 may not have been pulled from energy as a sweet formation packer			
RBP at 3,720', circulated casing with 130 bbls. fresh water and pressure tested casing (Continued On Back)			
I bereby certify that the information above is price and complete to the best of pry knowledge and belief.			
SIGNATURE Staff Assistant DATE06-94			
TYPE OR FRUNT NAME	Terry L. Harvey	~	
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON			
DISTRICT I SUPERVISOR			FED . 384
APPROVED BY		11114	DATE
CONDITIONS OF APPROVAL, IF ANY:			

from O' to 3,720'. Pressure decreased from 485 psi to 450 psi in 30 mins. Checked intermediate-production casing annulus and found 0 psi and no flow. Unable to locate surface-intermediate casing annulus riser. Released RBP at 3,720' and TOH with 120 jts. 2-3/8" tbg., SN, retrieving tool and RBP. TIH with a 2-3/8" SN, 3 jts. 2-3/8" 8rd tbg., 7" Baker tubing anchor catcher with 35,000# shear pins and 118 jts. 2-3/8" tbg. Dropped SV, pressure tested tbg. to 1,500 psi and retrieved SV. Removed 6" 900 manual BOP and adapter flange and installed 8-5/8" Larkin-Hinderliter tubinghead packing and slip assembly. Attempted to set TAC and found TAC would not set. Removed tubinghead packing and slipa ssembly and isntalled adapter flange and a 6" 900 manual BOP. TOH with 118 jts. 2-3/8" tbg. and 7" Baker TAC. Replaced TAC and TIH with 7" Baker TAC, with 35,000# shear pins and 118 jts: 2-3/8" tbg. Dropped SV, pressure tested tbg. to 1,500' psi and retrieved SV. Removed BOP and adapter flange and installed 8-5/8" Larkin-Hinderliter tubinghead packing and slip assembly. Set TAC at 3,676', with 12,000# tension and SN at 3,770'. TIh with a 2" x 1-1/4" x 10' pump #A-1124, 3/4" x 2' pony rod, 137-3/4" sucker rods, 12-7/8" sucker rods, 3: 7/8" x 6' pony rods and a 1-1/4" x 16' polished rod with a 1-1/2" x 9' liner. Loaded tubing with fresh water and checked pump action. Cleaned Addation and rigged down pulling unit.

TEST after: Prod. 86.0., 11 MCFGRA & 72 6.W. IN 24 hrs

.¥ : . ₹

