

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04222
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	EUNICE MONUMENT SOUTH UNIT B
8. Well No.	852
9. Pool name or Wildcat	EUNICE MONUMENT; GRAYBURG-SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator P.O. Box 1150, Midland, TX 79702	4. Well Location Unit Letter <u>D</u> : <u>330</u> Feet From The <u>NORTH</u> Line and <u>990</u> Feet From The <u>WEST</u> Line Section <u>11</u> Township <u>20S</u> Range <u>36E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: MILLED OUT 5" LINER, PERFD, ACZD ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH W/PROD EQPT. ATTEMPTED TO ESTAB CIRC-PMP 200 BBLS. NO CIRC; CAP 134 BBLS. SPOT 50 SX CMT IN LINER; TAG CMT @ 3826'. ATTEMPTED TO ESTAB CIRC-PMP 160 BBLS. NO RETURNS; CAP 134 BBLS. PPD 50 SX CMT; WOC, TEST 100#. TAG CMT @ 3400'; DRLD CMT TO 3920'. MILLED 5" LINER 3760'-3860'. REAMED HOLE 3763'-4000'. PERFD 3773'-3796' W/2 JHPF; PERFD 3681'-3761' W/4 JHPF. ACZD W/6000 GALS RESISOL II & 6000# TRIMIX SALT. SWABBED. RIH W/TBG, PUMP & RODS; PKR @ 3644'. RETURNED WELL TO PRODUCTION.

WORK PERFORMED 2/7/97 - 2/24/97

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE TECHNICAL ASSISTANT DATE 3/19/97
TYPE OR PRINT NAME J. K. RIPLEY TELEPHONE NO. (915)687-7148

(This space for State Use)

DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

MAR 25 1997

