

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSerial Number **046164-1**
Hazel Wolff Andrews - Lease
Lease or Permit.....

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT RECORD OF SHOOTING.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		RECORD OF PERFORATING CASING.....	
NOTICE OF DATE FOR TEST OF WATER SHUT-OFF.....	X	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING.....	
REPORT ON RESULT OF TEST OF WATER SHUT-OFF.....		NOTICE OF INTENTION TO ABANDON WELL.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO SHOOT.....		SUPPLEMENTARY WELL HISTORY.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 5, 1937

, 19

Following is a ~~notice of intention to do work~~
report of work done } on land under ~~permit~~
lease } described as follows:

New Mexico	Lea	Monument
(State or Territory)	(County or Subdivision)	(Field)
Well No. 6	0 SW 1/4 SW 1/4	12 20 36
	(1/4 Sec. and Sec. No.)	(Twp.) (Range) (Meridian)

The well is located **660'** ft. **[N]** of **South** line and **660'** ft. **[E]** of **West** line of sec. **12 - 20 - 36**

The elevation of the derrick floor above sea level is ft.

DETAILS OF PLAN OF WORK

DUPLICATE

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

3-5/8" 32# 8--Thd. New Seamless casing was set in this well at 2360' and cemented by the Halliburton Method with 600 sacks.**Casing and fittings will be tested with 1200# pump pressure and allowed to stand undisturbed for thirty minutes. If no drop in pressure results the cement will then be drilled out of the casing and the same test of 1200# pump pressure will again be applied and allowed to stand undisturbed for thirty minutes. If no drop in pressure results the drilling will then be resumed.**Approved
(Date)Company **Amerada Petroleum Corporation**By **J. A. Starky**Title
GEOLOGICAL SURVEYTitle **Farm Boss**

Address

Address **Monument, New Mexico**

NOTE.—Reports on this form to be submitted in triplicate to the Supervisor for approval.