

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSerial Number 046864-A
Hazel Wolff Andrews-Lease
Lease of Permit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT RECORD OF SHOOTING.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		RECORD OF PERFORATING CASING.....	
NOTICE OF DATE FOR TEST OF WATER SHUT-OFF.....	X	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING.....	
REPORT ON RESULT OF TEST OF WATER SHUT-OFF.....		NOTICE OF INTENTION TO ABANDON WELL.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO SHOOT.....		SUPPLEMENTARY WELL HISTORY.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 22, 1937, 19Following is a ~~notice of intention to do work~~
report of work done on land under ~~report of work done~~
lease described as follows:

<u>New Mexico</u>	<u>Lea</u>	<u>Monument</u>
(State or Territory)	(County or Subdivision)	(Field)
Well No. <u>6</u>	<u>C SW 1/4 NW 1/4</u>	<u>12</u>
	(1/4 Sec. and Sec. No.)	(Twp.)
		<u>20</u>
		(Range)
		<u>36</u>
		(Meridian)

The well is located 660' ft. N of South line and 660' ft. E of West line of sec. 12 - 20 - 36

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF PLAN OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

6-5/8" 20# 10-Tnd. New Seamless casing was set in this well at 3754' and cemented by the Halliburton Method with 100 sacks.

Casing and fittings will be tested with 1200# pump pressure and allowed to stand undisturbed for thirty minutes. If no drop in pressure results the cement will then be drilled out of the casing and the same test of 1200# pump pressure will again be applied and allowed to stand undisturbed for thirty minutes. If no drop in pressure results the drilling will then be resumed.

DUPLICATE

Approved _____
(Date)Company Amerada Petroleum CorporationBy J. A. StarkeyTitle _____
GEOLOGICAL SURVEYTitle Farm Boss

Address _____

Address Monument, New Mexico

NOTE.—Reports on this form to be submitted in triplicate to the Supervisor for approval.