SANTA FE			EW MÉVI		CUNCEDA	ATION CO	MISSION	FORM C-103
FILE U.S.G.S. LAND OFFICE						DRTS ON 1		(Rev 3-55)
TRANSPORTER PRORATION OFFIC OPERATOR	GAS					as per Commis		106)
ame of Compa	ny rede Petrol	eun Cerperatien	1	Add	lress Dre	wer "D", M		
ease W.P.	Byrd	W	Vell No. 2	Unit Lett	er Section	Township 20-5		ange 36-8
ate Work Perf		Pool Menand	ent			County	Les	
					ck appropria			
	Drilling Operat		sing Test a nedial Work	nd Cement	Job [Other (Exp	lain):	
] Plugging		, nature and quantity o			results obta	ined.		<u> </u>
		-	Patitio			Company		
Witnessed by	tis A. Gold			rn Bess		La construction of the second s		nam Corporation
Witnessed by	tis A. Gel		For LOW FOR	REMEDIA	AL WORK R			nm Cerperation
Cur D F Elev.	T	FILL IN BE	For LOW FOR	REMEDIA	AL WORK R	Amorai EPORTS ONI Producing In	.Y nterval	Completion Date 1-30-37
Cur D F Elev. 35661	Т	FILL IN BE	LOW FOR	REMEDIA GINAL WE	LL DATA	Producing Ir 3791 - eter	.Y nterval 3880 1 Oil String	Completion Date 1-30-37 Depth
Cur D F Elev. 35661 Tubing Diame 2-7/8	ter	FILL IN BE	LOW FOR	REMEDIA GINAL WE	LL DATA	Producing Ir 3791 - eter	.Y nterval 3880 1 Oil String	Completion Date
Cur D F Elev. 35661 Tubing Diame 2-7/8	ter	FILL IN BE	LOW FOR	REMEDIA GINAL WE TD Oil	LL DATA String Diam	America E PORTS ONL Producing In 3771 eter /8 °CD	.Y nterval 3880 1 Oil String	Completion Date 1-30-37 Depth
D F Elev. 35661 Tubing Diame 2-7/8 Perforated Int Open Hole Int	ter (D) ISUE terval(s)	FILL IN BE	LOW FOR ORI PB	REMEDIA GINAL WE TD Oil	LL DATA	Amerad E PORTS ONL Producing In 3771	.Y nterval 3880 1 Oil String 37	Completion Date 1-30-37 Depth 91 :
D F Elev. 35661 Tubing Diame 2-7/8 Perforated Int Open Hole Int	terval	FILL IN BE	RESU	REMEDIA GINAL WE TD Oil Pro	LL DATA	Ameria E PORTS ONL Producing In 3771 - eter /8" CD hation(s) Grayburg -	Y aterval 3880 1 Oil String 37 Sen Andre	Completion Date 1-30-37 Depth 91 :
Cur D F Elev. 35661 Tubing Diame 2-7/8 Perforated Int Open Hole Int 3791 Test	terval	FILL IN BE	RESU	REMEDIA GINAL WE TD Oil	LL DATA String Diam 6-5 oducing Form	Amerad E PORTS ONL Producing In 3771	.Y nterval 3880 1 Oil String 37	Completion Date 1-30-37 Depth 91 : Gas Well Poten
D F Elev. 35661 Tubing Diame 2-7/8 Perforated Int Open Hole Int 3791	T terval(s) terval Date of	FILL IN BE	RESU	REMEDIA GINAL WE TD Oil Pro JLTS OF W s Productio	LL DATA String Diam 6-5 oducing Form	America E PORTS ONL Producing In 3771 - eter 81 CD hation(s) Grayburg - Production	.Y hterval 3880 1 Oil String 37 Sen Andre GOR	Completion Date 1-30-37 Depth 91 : Gas Well Poten
Cur D F Elev. 35661 Tubing Diame 2-7/8 Perforated Int Open Hole Int 3791 Test Before	T terval a 3850 i Date of Test	FILL IN BE	RESU	REMEDIA REMEDIA GINAL WE TD Oil Oil Pro ULTS OF W s Productio MCFPD 5	LL DATA String Diam 6-5 oducing Form VORKOVER on Water	America E PORTS ONL Producing In 3771 eter /8" CD hation(s) Creyburg Production B P D 1977 O	Y hterval 3880 1 Oil String 37 San Andre GOR Cubic feet/B 510 271	Completion Date 1-30-37 Depth 91 : 6 6 6 6 6 6 6 6 6 1 6 1 6 1 6 1 1 1 1 1 1 1 1 1 1 1 1 1
Cur D F Elev. 35661 Tubing Diame 2-7/8 Perforated Int Open Hole Int 3791 Test Before Workover After	T terval 3850 1 Date of Test 12-1-61 12-18-61	FILL IN BE	RESU	REMEDIA REMEDIA GINAL WE TD Oil Oil Pro ULTS OF W s Productio MCFPD 5 13	LL DATA String Diam 6-5, oducing Form VORKOVER on Water	America E PORTS ONL Producing In 3771 eter /8" CD hation(s) Creyburg Production B P D 1977 O	Y hterval 3880 1 Oil String 37 San Andre GOR Cubic feet/B 510 271 ormation given	Completion Date 1-30-37 Depth 91 : Gas Well Poten
D F Elev. 35661 Tubing Diame 2-7/8 Perforated Int Open Hole Int 3791 Test Before Workover After	T terval Date of Test 12-1-61 12-18-61 OIL CONSE	FILL IN BE	RESU	REMEDIA REMEDIA GINAL WE TD Oil Pro ILTS OF W s Productio MCFPD 5 13	LL DATA	America E PORTS ONL Producing In 3791 eter /8" CD hation(s) Grayburg Production B P D 197 0 ijfy that the inf	Y hterval 3880 1 Oil String 37 San Andre GOR Cubic feet/B 510 271 ormation given	Completion Date 1-30-37 Depth 91 : 6 6 6 6 6 6 6 6 6 1 6 1 6 1 6 1 1 1 1 1 1 1 1 1 1 1 1 1
Cur D F Elev. 35661 Tubing Diame 2-7/8 Perforated Int Open Hole Int 3791 Test Before Workover After Workover	T terval Date of Test 12-1-61 12-18-61 OIL CONSE	FILL IN BE	RESU	REMEDIA REMEDIA GINAL WE TD Oil Pro ILTS OF W s Productio MCFPD 5 13	LL DATA	America E PORTS ONL Producing In 3791 eter /8" CD hation(s) Grayburg Production B P D 197 0 ijfy that the inf	Y nterval 3880 1 Oil String 37 Sen Andre GOR Cubic feet/B 510 271 ormation given	Completion Date 1-30-37 Depth 91 • 6 6 6 6 6 6 6 7 7 7 7 7 7 7 7 7 7 7 7 7