				Form	C-103
	,			(Revise	d 3-55)
NEW MEXIC	CO OIL CONSERVA	TION CO	MMISSION	· ·	· .
MISCE	LLANEOUS REPC	RTS ON	WELLS	FICE OCC	
	1				
(Submit to appropriate		por 001	957 007 7	PM 3:58	н
COMPANY Gulf (11 Corporation - R	x 2167. H	lobbs, New M	exico	
	(Address				
LEASE Graham State "H"	WELL NO. 2	UNIT	<u>M S 13</u>	T 20-S	R 36-5
DATE WORK PERFORMEI	6-16 thru 10-1-5	POOL	Monument		
			PTV Standy AU		
This is a Report of: (Chec	k appropriate bloc	<) T	Results of	Test of Cas	sing Shut-off
	. appropriate site		_		
Beginning Drilling	Operations		Remedial	Work	
	,				
Plugging			Other	· · · · ·	
Detailed account of work do	one, nature and qu	antity of 1	materials u	sed and res	ults obtained.

Fracture treated as follows:

- Pulled tubing and packer. Ran Gamma Ray Neutron survey.
 Ran 2-7/8* tubing with packer at 3774'. Treated open hole formation with 13,860 gallons refined oil with ## sand per gallon. Pulled tubing and packer.
- 3. Ran 2-3/8" tubing with pasker at 3768'. Swabbed. Pulled tubing and packer. Ran 120 joints 2-7/8" tubing at 3786' and rods and pump.

FILL IN BELOW	FOR REMED	IAL WORK	REPORTS OF	NLY	
Original Well Dat	a:				
DF Elev. 3551:	TD 3875	PBD 🕳	Prod. Int.	3808-38751 Comp	ol Date 9-18-37
Tbng. Dia 2-3/8"	Tbng Depth	3864 0	il String Dia	5-1/2 Oil Stri	ng Depth 37594
Perf Interval (s)					
Open Hole Interva	al 3759-3875	Produc	ing Formation	n (s) Eunice	
RESULTS OF WC	RKOVER:			BEFORE	AFTER

DEFORE	AL LEN		
None	10-3957		
	<u></u>		
	183		
	678		
	4073		
Gulf Oil Corporation			
(Company)			
I hereby certify that the information given above is true and complete to the best of			
my knowledge. Name 736	when		
Position Area Supt. of Pro	d.//		
Company Galf Oll Corporat	ion		
	None None Calf Oil Corporation (Comp I hereby certify that the info above is true and complete to my knowledge. Name Position Area Supt. of Pro- End Oil Corporation		