

CHEVRON U.S.A. INC.
DISPOSAL/INJECTION WELL
PRESSURE TEST REPORT
NEW MEXICO

RECEIVED
DEC 16 10 37 AM '93

1. LEASE NAME: EMSUB
2. WELL NO: 875-w.c
3. LOCATION: UNIT E SEC 14 T 20-S R 36-E
4. COUNTY: Lea
5. REASON FOR TEST: ☒ INITIAL TEST PRIOR TO INJECTION
☐ AFTER WORKOVER
☐ FIVE YEAR TEST
☐ OTHER (SPECIFY) _____

6. DATE OF TEST: 11-18-93

7. TEST PRESSURE:

TIME	TUBING	CASING	SURFACE CASING
INITIAL	<u>open</u>	<u>320</u>	<u>Ø</u>
15 MIN.	<u>Ø</u>	<u>320</u>	<u>Ø</u>
30 MIN.	<u>Ø</u>	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

8. TEST WITNESSED BY OCD: ☐ YES ☒ NO
IF YES, NAME OF OCD REP. Notified 11-17-93

9. OPERATOR COMMENTS ON TEST: Set Sur-hoc Rkr. w/ pumpout plug
Circ Rkr fluid Engage on/off Tool Test CSG

10. WELL STATUS:

☒ ACTIVE ☐ TEMPORARILY ABANDONED ☐ OTHER (SPECIFY) _____

11. CHEVRON REPRESENTATIVE: BE. Cone Workover Rep.
NAME TITLE

Bobby E Cone
SIGNATURE