

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
Amoco Production Company
3. ADDRESS OF OPERATOR
P. O. Box 68, Hobbs, NM 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL X 1980' FWL, Unit F
AT TOP PROD. INTERVAL: Sec. 24, T-20-S, R-36-E
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

- ☐
☐
☒
☐
☐
☐
☐
☐
☐

5. LEASE
LC-031736 (a)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Gillully A Federal *Blk 2*
9. WELL NO.
13
10. FIELD OR WILDCAT NAME
Eunice GSA-Oil
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
24-20-36
12. COUNTY OR PARISH
Lea
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3568' RDB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in service unit 4-14-82. Tagged fill at 3629 with tubing, then pulled tubing. Set a treating packer at 3391' and tailpipe landed at 3485'. Pumped 3000 gal 15% NEFE HCL acid with 1000 SCF N2 per bbl in 2 equal stages. Flushed with 18 bbl 2% KCL water with 1000 SCF N2 per bbl. Pulled packer and tailpipe. Ran 2-7/8" tubing and seating nipple to 3607'. Swabbed for 19 hrs. and recovered 105 BLW with slight show of gas. Moved out service unit 4-19-82 and moved in swab unit. Swabbed for 24 hr. and recovered 54 BLW with slight show of gas. Moved out service unit 4-22-82. Well currently shut-in.

0+4-USGS, R 1-HOU 1-SUSP 1-CLF

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *Cathy L. Ferman* TITLE *Ast. Adm. Analyst* DATE *6-17-82*

ACCEPTED FOR RECORD

(is space for Federal or State office use)

APPROVED BY (Orig. Sgd.) *PETER W. CHESTER*
CONDITIONS OF APPROVAL *JAN 19 1983*

TITLE DATE

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

RECEIVED
JAN 21 1960
C. E. J.
NOELL OFFICE