

Form 9-831a

(Nov. 1930)

Indian Agency.....

(SUBMIT IN TRIPLICATE)

U. S. Land Office Las CrucesLease or permit No. 048741

Allottee.....

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease No. Louis C. Popeano

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO REPAIR REPAIR WELL.....	X	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas December 7, 1939

Well No. 6 is located 660 ft. from [N] line and 660 ft. from [E] line of sec. 35

NE/4 of NE/4 of Sec. 35 20-South 36-East
(1/4 Sec. and Sec. No.) (Twp.) (Range)

Eunice Lee New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5566 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

To pull well with oil, pull 2" tubing and re-run tubing and set Robinson 3-in-1 Rubber Anchor Packer at 3787' to reduce gas-oil ratio. Present producing gas-oil ratio 62,388.

RECEIVED
 DEC 11 1939

I understand that this plan of work must receive approval in writing by the Geological Survey before work can be commenced.

Company HUMBLE OIL & REFINING COMPANY

Address Box 1600 - Midland, Texas

By [Signature]
 Title Division Superintendent